
Record Provider	Fleet #	Serial No.	Location of Service Date	_	laim No.	Claim No. Date Claim Rcvd.	Summary of Problem(s)	Associated Claim
CAT	0009	2KS27780	Tri-State Truck Center	3/27/2003 Q471616	471616	5/13/2003	Intake wheel came apart into housing, 5/13/2003 housing damaged.	
Black Binder/Trans-Spec			Trans-Spec	7/28/2003			Replace clutch.	
Black Binder			N/A	12/16/2003			Replaced flywheel housing.	
CAT			Minuteman Trucks, Inc	4/1/2004 Q705679	705679	4/14/2004	Oil leaks due to gasket failure. Leaking from between block & gear housing lower 4/14/2004 left corner drain coolant system.	
Black Binder/Trans-Spec			Trans-Spec	4/30/2004			Take down drive shaft, tap out bolt holes, install spring kit, put shaft up.	
CAT			Southworth-Milton	11/9/2004 Q913666	13666	Broken fly rise on ho 12/23/2004 replaced.	Broken flywheel housing caused by stress rise on housing. Flywheel housing replaced,	
Minuteman Trucks	6100	2KS27897	Minuteman Trucks, inc	1/24/2002	,		Transmission grinds in every gear - thrust washer broken up in transmission. Install new transmission, PTOs, & bolts (?).	
CAT			Southworth-Milton	3/14/2003 Q435978	35978	3/25/2003	During dropped valve repair, found #6 3/25/2003 liner scored in 4 place	0435075
САТ			Southworth-Milton	3/17/2003 Q435975	35975	Engine damage 3/25/2003 & turbo.	Engine skip caused by #2 valve dropped - damaged piston, injector, cooling jet, head & turbo.	
Black Binder/Trans-Spec			Trans-Spec	6/30/2003	-		R&R clutch, install new PTO shaft, repair blower motor, remove bypass fuel cooler.	
Black Binder/Trans-Spec			Trans-Spec	12/16/2003			Fiywheel Housing Replaced.	
Black Binder/Trans-Spec			Trans-Spec	1/28/2004			Right steer spring broken.	
Black Binder/Trans-Spec			Trans-Spec	4/22/2004			Take down drive shaft, tap out boit holes, install spring kit, put shaft up.	
CAT Block Bindon			Tri-State Truck Center	5/22/2004 Q756259	56259	6/21/2004	Gear case to joint block gasket leaking. 6/21/2004 Broken gear case bolt behind CAM gear.	
מונים אם			NA	8/16/2004			Flywheel housing and valve.	
CAT - SIMSi			Tri-State Truck Center	Dealer Cla 9/11/2004 TS109016	Dealer Claim TS109016	and the fair	Removed flywheel housing & found dowel pins walked out of the block & caused flywheel bolts to seize up. Re-install flywheel w/ new hardware.	
CAT			Tri-State Truck Center	9/11/2004 Q819575	9575	9/14/2004 [1	#2 cylinder not firing. Only the injector push rod was still connected to 32 injector 9/14/2004 intake & exhaust missing	0821783
САТ		-	Tri-State Truck Center	9/11/2004 Q821763		8	l pins walking	O819575
		•	Tri-State Truck Center	10/13/2004 Q855549		1st: 10/25/2004; 2nd: F	oins walking	
CAT	6200	2KS27878	Minuteman Trucks, Inc	4/4/2000 Q724887	4887	7/6/2000 T	7/6/2000 Truck runs erratic & light (?)	



CAT			Minuteman Trucks, Inc	4/27/2000	4/27/2000 Q703806	6/5/200	Engine dies/ cuts out intermittently. Found 2 logged inactive codes. Replaced sensor 6/5/2000 at crank.	
CAT			Minuteman Trucks, Inc	2/27/2003	2/27/2003 0441650	4/1/2003		
Black Binder/Trans-Spec			Trans-Spec	4/30/2004			Take down drive shaft, tap out boit holes, install spring kit, put shaft up.	
Minuteman Trucks	6300	2KS27936	Minuteman Trucks, Inc	9/22/2000			Transmission will not shift - clutch defective.	
Minuteman Trucks			Minuteman Trucks, Inc	7/13/2001			Vibration felt through transmission shifter at highway speeds - rear case chewed up at rear bags as well as low gear & washers due to loose voke nut.	
Minuteman Trucks			Minuteman Trucks, Inc	8/31/2001			Transmission failure - transmission has no oil & 4 bolts missing from bottom PTO cover & 2 broken bolts.	
Minuteman Trucks			Minuteman Trucks, Inc	9/7/2001			Replace transmission that failed due to lack of lube - continuation of above (831/01).	
CAT			Minuteman Trucks, Inc	12/7/2001 Q130439	Q130439	2/8/2002	Found 9 bolts broken & 3 loose in flywheel. Replace broken bolts & reinstail 2/8/2002 new housing.	
CAT			Southworth-Milton	9/9/2002 0296409	Q296409	9/19/2002	10 of 12 flywheel hsg mount bolts sheared off - housing is damaged from chaffing 9/19/2002 against block. Replace hsg & all hardware.	
САТ			Minuteman Trucks, Inc	2/6/2003 Q420855	2420855	3/4/2003		0446735
CAT			Minuteman Trucks, Inc	2/6/2003 Q446735	2446735	4/7/2003		Q420855, Q473232, Q528561
CAT			Minuteman Trucks, Inc	2/6/2003 Q473232	1473232	5/15/2003	E -	Q420855, Q528561, Q446735
CAT			Minuteman Trucks, Inc	2/6/2003 Q528561	1528561	8/11/2003	Housing broken, causing bolts to break off. 10 of 12 flywheel housing bolts broken off in back of engine block. Bolts needed to be drilled out & replaced. Hydraulic pump mounting plange worn where heads 8/11/2003 of botts were loose & should be repaired.	0420855
Black Binder/Trans-Spec			Trans-Spec	8/21/2003			T	

Black Binder/Trans-Spec Black Binder/Trans-Spec Black Binder/Trans-Spec			-	check flywheel housing for possible	
k Binder/Trans-Spec Binder/Trans-Spec		Trans-Spec	10/27/2003	 demage (starter is also not engaging correctly - could be housing boits). Replace flywheel housing, gasket kit, down in a such starter of both starter of the such sta	
k Binder/Trans-Spec		Trans-Spec	11/17/2003	Fluidad Livington Doubles a	
worth-Milton		Trans-Spec	4/30/2004	Drop drive shaft, tap out bolt holes, install spring K. & reinstall drive shaft	
		Southworth-Milton	3/22/2005	Repair engine under warranty. Flywheel housing lose bir flywheel housing lose bir flywheel hag. bolts are housing lose bir flywheel hag.	
Black Binder/Trans-Spec 6700 2	2KS27904	Trans-Spec	2/11/2003	D&B All Mah	
Black Binder/Trans-Spec		Trans-Spec	6/30/2003	D&D first	
Black Binder/Trans-Spec		Trans-Spec	7/9/2003	Refruito - sent old cartidge in for	
		Minuteman Trucks, Inc	8/25/2003 Q550638	Exhaust valve broken & wedged itself in head, damaging injector & cylinder wall on 9/15/2003 #6, #8 injector broken when when when the beath	
Minuteman Trucks		Minuteman Trucks, Inc	9/10/2003	Engine skip/knock - install new rear syncro assy (?) & auxiliary drive gear in	
Black Binder/Trans-Spec		Trans-Spec	9/19/2003	Doubles Case	
Black Binder/Trans-Spec		Trans-Spec	4/30/2004	Drop drive shaft, tap out boit holes, install	
Black Binder/Southworth- Milton Black Binder		Southworth-Milton	8/23/2004	Replaced flywheel housing and electric	
		N/A	8/25/2004	Dropped valve	
		Southworth-Milton	10/26/2004 (Oosesage	Jake housing & all valves broken on #3 cylinder. #3, 4, 5 pistons damaged. Center section of exhaust manifold cracked/separating. Turbo hot housing	T
		Southworth-Milton	11/1/2004 Q981768	2/9/2005 cracked. Damaged threads on oil return of turbo	
		Southworth-Milton	2/1/2005 Q956307	2/9/2005 Renlaces manifold splitting - was faulty.	
Black Binder/Trans-Spec 6800 2K	2KS27955	Trans-Spec	2/1/2003	R&R clutch	
Black Binder/Trans-Spec		Trans-Spec	5/9/2003	Truck skipping, grease 5th wheel, #4	
Black Binder/Trans-Spec		Trans-Spec	5/6/2004	Remove driveshaft, tap bolt holes, install	
Black Binder		Tri-State Truck Center	6/29/2004	spring kit, & reinstall drive shaft.	

							of down nin effection or the father		
			Tri-State Truck Center	7/29/2004	7/29/2004 0785574				
			Tri-State Truck Center	A00C/PC/7	7/20/2004 OZBEEGO	402/S217	Front structure leaking at joint block gasket. CAM thrust pin broken. Replace	Q785569	
						\$02 (82)	Figure 1. Basker. Holes elongated & dowel pins are walked dout of block into housing. Removed 9 broken flywhael housinn holts Installed	Q785574	
			Tri-State Truck Center	7/29/2004	7/29/2004 Q808267	8/30/2004		7000000	
			Tri-State Truck Center	8/27/2004 Q806567	Q806567	8/27/2004	#4 exhaust valve broke, causing #4 piston to break apart, causing the connection rod to smast the liner, which damaged the such rock.	L 63363, C 835/4	
			Southworth-Milton	11/18/2004 Q017179	Q017179	4/13/2005	Intake valve springs #1, 5, & 6 broken.		
Minuteman Trucks	0069	2KS28378	Minuteman Trucks, Inc	8/28/2000			Check for transmission falling out. Found bell crank housing loose		
Minuteman Trucks			Minuteman Trucks, inc	8/30/2000			Transmission cooler lines rubbing against exhaust system		
			Tri-State Truck Center	5/8/2002	5/8/2002 0201393	5/9/2002	Turbo wheel/ shaft broken, causing loss of 5/9/2002 power. Replaced turbo.		
Black Binder/Trans-Spec			Trans-Spec	5/19/2003			Clutch or clutch brake not working; starting falling out.		
			Minuteman Trucks, Inc	8/13/2003 Q541301	Q541301	8/29/2003	#4 exhaust valve broken. Replace #1 8/29/2003 injector b/c exhaust valve hit tip of injector. Q571392	Q571392	
			Minuteman Trucks, Inc	8/13/2003 Q571392	0571392	10/14/2003	#4 exhaust valve broken. Replace #1 10/14/2003 injector bic exhaust valve hit tip of injector. Q541301	Q541301	
Black Binder/Trans-Spec			Trans-Spec	8/28/2003			Check all clamps, and water & oil levels.		
Black Binder/Trans-Spec			Trans-Spec	1/6/2004			Check front end out.		
Black Binder/Trans-Spec			Trans-Spec	4/26/2004			Take down drive shaft, tap out bolt holes, install spring kit, but shaft up.		
			Tri-State Truck Center	7/29/2004 Q785557	2785557	7/29/2004 n	t block er. Installed	0785564	
			Tri-State Truck Center	7/29/2004 Q785564	1785564	7/29/2004 d	raining bolts broken. mshaft & found all bearings camshaft,	078557	
			Tri-State Truck Center	7/29/2004 Q808432	808432	8/30/2004 d	ts broken. ound all bearings	0785557	
								K1 0000 r	

CAT			Southworth-Milton	8/17/2004	8/17/2004 (093/105	1113/2001	Broken flywheel housing. 8 bolts were sheared & dowels had backed out into the bellhousing & were flush w/ surface of bellhousing. Installed new dowels & plugs in bellhousing to prevent them from working out of block.	99
Black Binder/Trans-Spec 7100	7100	2KS27844	Trans-Spec	7/29/2003			Rebuilt jake brake & adjusted all valves.	0801
Black Binder/Trans-Spec			Trans-Spec	10/8/2003			Flywheel Housing Replaced.	
Black Binder/Trans-Spec			Trans-Spec	12/23/2003			9th gear slips loaded going uphill.	
Black Binder/Trans-Spec			Trans-Spec	4/21/2004			Take down drive shaft, tap out boit holes, install spring kit, put shaft up.	
САТ			Tri-State Truck Center	5/27/2004 Q752306	Q752306	6/15/2004	Front structure leaking at joint 6/15/2004 blockgasket. CAM thrust pin broken.	
САТ			Tri-State Truck Center	6/30/2004 Q768541	Q768541	717/2004	Holes are elongated and dowel pins are walked out of block into flywheel housing. 0788525	0788525
САТ			Tri-State Truck Center	6/30/2004 Q788525	Q788525	8/4/2004	Holes are elongated and dowel pins are walked out of block into flywheel housing. 6/4/2004 Removed 9 broken flywheel housing boirs. O768547	0768541
САТ			Tri-State Truck Center	6/30/2004 Q821758	Q821758	9/16/2004	Holes are elongated and dowel pins are walked out of block into flywheel housing. 9/16/2004 Removed 9 broken flywheel housing boths	0768541
Minuteman Trucks	7400	2KS27905	Minuteman Trucks, Inc	1/31/2001			No power flow to ECM circuits - repair harness.	
CAT			Minuteman Trucks, Inc	9/15/2003 Q577445	2577445	10/23/2003	Radiator empty, coolant in oil - caused by valve failure. #3 cylinder badly damaged, causing damage to piston/cylinder block 10/23/2003 (was cracked).	
Minuteman Trucks			Minuteman Trucks, Inc	10/21/2003	_		Replace clutch assembly & machine flywheel.	
Black Binder/Trans-Spec			Trans-Spec	5/6/2004	·		Take down drive shaft, tap out bolt holes, install spring kit, put shaft up.	
САТ			Tri-State Truck Center	9/30/2004 Q834570	2834570	9/30/2004	Front structure leaking at joint 9/30/2004 blockgasket. CAM thrust pin broken.	Q834541
CAT			Tri-State Truck Center	9/30/2004 Q834561	2834561	9/30/2004	Dowel pins walked out of block in flywheel house & caused flywheel to come loose & 9/30/2004 break flywheel bolts.	
САТ			Tri-State Truck Center	9/30/2004 Q839701	1839701	10/6/2004	Gaskets are blown out on end sections at 10/6/2004 #6 & #1 cylinders in exhaust manifold.	
САТ			Tri-State Truck Center	9/30/2004 Q834541	1834541	9/30/2004	충	0834570
САТ			Tri-State Truck Center	11/27/2004 0910331	<u>1910331</u>	12/21/2004	g loose b/c flywheel are broken.	

	7500	2KS27000	After the second second				Engine skipped - found #5 injector was no
CAT		66619011	Minuteman Incks, Inc	2/22/2000	2/22/2000 Q646089	3/14/200	3/14/2000 good. Injector replaced.
i			willingerijan i rucks, inc	2/22/2000	2/22/2000 E573768	5/22/200	5/22/2000 Missing cyf. Refer to cal MFTS0008
Black Binder/Trans-Spec			Trans-Spec	12/10/2003	-		Flywheel Housing loose; tranny popping
Black Binder/Trans-Spec			Trans-Spec	4/20/2004			Drop drive shaft, tap tranny bolt holes,
				00707			Install spring kits, & reinstall drive shaft.
CAT			Southworth-Milton	1/12/2005	1/12/2005 Q012462	railed was o was	railed liywheel housing b/c the housing was cracked. Replace flywheel housing & 5 bolts.
k Binder/Southworth-	7600	2KS27877	Southworth-Milton	8/45/4008			Broken bolt in flywheel. Possible crack in
- X			Tri-State Truck Center	5/8/2002	5/8/2002 0201392	5/9/2002	
CAT			Southworth-Milton	5/20/2003 Q485909	Q485909	Found Sylinde Cylinde	Found a broken valve spring on #6 cylinder (intake) during front cover gasket
CAT			Southworth-Milton	5/27/2003 0485903	0485903	COCCITIO	Front cover gasket to cyl block leaking. Found one broken bolt behind Cam gear -
Black Binder/Trans-Spec			Trans-Chen	714 10000		0/4/2005	0/4/2003 nousing is damaged. Check belihouse for cracks: check dome
CAT			Dado-supi.	//14/2003			cover - send to Minuteman. Checked flywheel housing found a good
Black Binder/Trans-Spac			Iri-State Truck Center	7/17/2003 Q520633	Q520633	7/29/2003	7/29/2003 Replaced housing - Iourid & Grack. Oron shoft housing.
CAT			Trans-Spec	5/5/2004			Selected states and controlled install spring kit, and controlled states and controlled
			Tri-State Truck Center	8/4/2004 Q788612	Q788612	8/4/2004	8/4/2004 gasket. CAM thrust pin broken.
САТ			Tri-State Truck Center	8/4/2004 Q788618	2788618	8/4/2004	Holes are elongated and dowel pins are walked out of block into flywheel housing. 8/4/2004 Removed 9 broken flywheel housing bolts. Q788612
CAT			Tri-State Truck Center	8/4/2004 Q821762	1821762	9/16/2004	Holes are elongated and dowel pins are walked out of block into flywheel housing. 9/16/2004 Removed 9 broken flywheel housing botte.
CAT			Southwarth Milkon				ig falled (falling starter), owel holding flywheel & housing dislocated
CAT			Southworth-Milton	11/9/2004 (09/3373	913373	11/5/2004	11/5/2004 Replace starter.
Black Binder/Trans-Spec 7700		2KS28368	Trans-Spec	7/16/2001		7707677	Ranjara etaer mains
Black Binder/Trans-Spec			Trans-Spec	1/27/2003			Needs of the
Black Binder/Trans-Spec			Trans-Spec	10/9/2003			Chack front and
Black Binder/Trans-Spec			Trans-Spec	5/3/2004			Remove driveshaff, tap boit holes, install

CAT			Tri-State Truck Center	7/29/2004	7/29/2004 Q785584	Filwt Causi 7/20/2004 bolts	Flywheel housing bolts backing out causing flywheel to be loose. Replace		
CAT		·	Tri-State Truck Center	7/29/2004	7/29/2004 Q785580	7/29/2004	Front structure leaking at joint block gasket, at front gear case cover. Installed 7/29/2004 new gasket.	Q785580 Q785584	
CAT			Tri-State Truck Center	7/29/2004	7/29/2004 Q808275	. 8/30/2004	Holes are elongated & dowel pins are walked out of block into flywheel housing. Removed 9 broken flywheel housing bolts. Installed plugs in dowel bones to prevent this from walking out of the block.		T
CAT			Southworth-Milton	10/21/2004 Q944471	Q944471	1st: 1/27/2005; 2nd: 3/24/05		0944437	T-
			Southworth-Milton	10/25/2004 Q944437	Q944437	1st: 1/27/2005; 2nd: 3/4/05	Flywheel housing cracked & damaged cylinder block cause by loose flywheel housing. Replace bare block & flywheel housing.	7	
CAT 78	7800	2KS27861	Minuteman Trucks, Inc	11/8/2000	11/8/2000 Q833629		12/7/2000 Dipstick tube broken.	7444	
Minuteman Trucks			Minuteman Trucks, Inc	8/31/2001			Transmission noisey - main shaft & counter shaft gears all broken & pieces missing.		
CAT			Tri-State Truck Center	3/20/2003	3/20/2003 Q471602	5/13/2003	Intake wheel came apart into housing., 5/13/2003 shaft broken		
Black Binder/Trans-Spec			Trans-Spec	5/6/2003			#1, #2, & #6 injectors not firing. Replaced 3 bad injectors.		Τ
Black Binder/Trans-Spec			Trans-Spec	6/6/2003			Needs clutch - TR & TRL brake adjustment.		.
Black Binder/Trans-Spec			Trans-Spec	7/28/2003			Jake brake stays on; adjust all valves & injectors.		<u> </u>
САТ			Minuteman Trucks, Inc	2/12/2004 Q670585	Q670585	3/1/2004	Exhaust valve broken - damaged head. 3/1/2004 Found cylinder 4 dropped valves.		1
Black Binder/Trans-Spec			Trans-Spec	4/20/2004			Drop drive shaft, tap out bolt holes, install spring kit. & reinstall drive shaft		
- I			Tri-State Truck Center	5/26/2004 Q755769	Q755769	6/18/2004	6/18/2004 Gear case to joint block gasket leaking		Т
Minuteman Trucks 790	7900	2KS27956	Minuteman Trucks, Inc	7/21/2000			Noise from transmission area - frozen PTO shaft (?) that cause much gear damage. Install 18 new PTO studs to new transmission.		
Black Binder/Trans-Spec			Trans-Spec	3/14/2003			Renlace transfer numn		
САТ			Southworth-Milton	5/5/2003 Q475056	2475056	5/19/2003	Σ Σ		,
CAT			Southworth-Milton	5/7/2003 Q475076	2475076	Replaced 5/19/2003 PS50041.	& tapped head bolts as per	0475056	
Black Binder/Trans-Spec			Trans-Spec	4/21/2004		S)	Drop drive shaft, tap out bolt holes, install spring kit, & reinstall drive shaft.		,
CAT			Tri-State Truck Center	5/12/2004 Q753976	2753976	6/17/2004 F	Gear case to joint block gasket leaking. 6/17/2004 Replace seals & gaskets.		

Tri-State Truck Center 7729/2004 G1868563 7729/2004 7729	CAT			i	ļ 			Flywheel housing bolts backing out	
Tri-State Truck Center 7729/2004 0206236 8/30/2004				In-State Iruck Center		04 Q785553	7/29/20	04 bolts,	Q808296, Q785550
Southworth-Milton S/12/2004 G006756 S/12/2004				Tri-State Truck Center	Oucibalz	000		Holes are elongated & dowel pins are walked out of block into flywheel housing. Removed 9 broken flywheel housing bolts. Installed plugs in dowel bones to prevent	
Southworth-Milton S/24/2004 G290726 12/10/2004 G290726 12/10/2004 G290726 12/10/2004 G290726 12/10/2004 G290726 12/10/2004 G290726		· 			00716711	4 0008296	8/30/200	8/30/2004 plns from walking out of block.	Q785550
8000 2KS27857 N/A 4/17/2003 CP577409 Pead Claim		-		Tri-State Truck Center	7/29/200-	4 Q785550	7/29/200	#2 intake valve damaged, which damaged 7/29/2004 the turbo. Replaced #1.8 #2 adjusted.	
NIA A17/2003 CF77409 Dealer Claim				Southworth-Milton	8/24/2004	4 0900726	12/10/200	1	Q/85553, Q808296
NIA 6/27/2003 182179 Dealer Claim	SIMSi	8000	2KS27857	N/A	4/17/2003	Deal Claim 3 CF77409			73001 ZO
Spec	SIMSi			N/A	6/27/2003	Dealer Claim 182179		Unit Injector	
Spec	SIMS			N/A	6/27/2003	Dealer Claim OTH18606		Init injector	
Spec Trans-Spec 10/16/2003 Spec Trans-Spec 3/8/2004 Spec Trans-Spec 3/8/2004 Spec Trans-Spec 4/21/2004 Spec Southworth-Milton Southworth-Milton T/6/2004 MT6/16211 Spec Trans-Spec 4/22/2004 G755728 Sylvation Tri-State Truck Center Sylvation Sylv	Binder/Trans-Spec			Trans-Spec	9/29/2003			Flywheel housing broken - truck out of service	
Southworth-Milton S/12/2004 S/21/2004 S/22/2004 S/22/2005 S/22/2005 S/22/2005 S/22/2004 S/22/2005 S/22/2004 S/22/2005 S/22/2004 S/22/2005 S/22/200	3inder/Trans-Spec		-	Trans-Spec	10/16/2003			Tranny out of truck. Replaced clutch &	
Southworth-Milton 6/11/2004 Q809570 8/31/2004 Southworth-Milton Southworth-Milton T/6/2004 MT616211 Southworth-Milton T/6/2004 MT616211 Tri-State Truck Center S/26/2004 Q755728 G/18/2004 Dail Claim C/18/2004 Dail Claim C/18/2005 Dail Claim C/18/2005 Dail Claim C/18/2005 Dail Claim C/18/2006 Dail Claim C/18/200	3inder/Trans-Spec			Trans-Spec	3/8/2004			Flywheel housing cracked & loose -	
8100 2KS28276 Minuteman Trucks, Inc 5/12/2004 QR09670 8/31/2004 Tri-State Truck Center 6/28/2004 G755728 6/18/2004 Tri-State Truck Center 6/28/2004 G755728 6/18/2004 Tri-State Truck Center 6/28/2004 Southworth-Milton 1/20/2005 G006706 4/1/2005	inder/Trans-Spec			Trans-Spec	4/21/2004			Drop drive shaft, tap out boit holes, install	
8100 2KS28276 Minuteman Trucks, Inc 5/12/2004 MT616211 Tri-State Truck Center 6/28/2004 G755728 6/18/2004 Tri-State Truck Center 6/28/2004 G755728 6/18/2004 Tri-State Truck Center 6/28/2005 G006706 4/1/2005 Minuteman Truck Center 6/28/2005 G006706 4/1/2005				Southworth-Milton	6/11/2004	010000		spring kit, & reinstall drive shaft. Flywheel housing cracked, Replaced	
8100 2KS28276 Minuteman Trucks, Inc 5/12/2000 Q725053 7/6/2000 Dec Trans-Spec 4/22/2004 7/6/2004 7/6/2004 Tri-State Truck Center 5/26/2004 Q755728 6/18/2004 Tri-State Truck Center 6/28/2004 6/18/2004 Southworth-Milton 1/20/2005 Q006706 4/1/2005	IMSi		-	Southworth-Milton	7/6/2004	Deal Claim MT616211	8/31/2004	8/31/2004 Cylinder block under warranty. Flywheel housing	
Trans-Spec 4/22/2004 Tri-State Truck Center 5/26/2004 Q755728 6/18/2004 Tri-State Truck Center 6/28/2004 Tri-State Truck Center 6/28/2004 Southworth-Milton 1/20/2005 Q006706 4/1/2005		8100	2KS28276	Minuteman Trucks, Inc	5/12/2000	2725053	7/8/2000	Truck hesitates & cuts out intermittently -	
Tri-State Truck Center 5/26/2004 Q755728 6/18/2004 Tri-State Truck Center 6/28/2004 Tri-State Truck Center 6/28/2004 Southworth-Milton 1/20/2005 Q006706 4/1/2005	nder/Trans-Spec			Trans-Spec	4/22/2004		000	Drop drive shaft, tap out boit holes, install	
Tri-State Truck Center 6/28/2004 Tri-State Truck Center 6/28/2004 Southworth-Milton 1/20/2005 Q006706 4/1/2005				Tri-State Truck Center	5/26/2004	2755728	8/18/2004	Gear case to block joint leaking oil.	
Southworth-Milton 1/20/2005 Q006706 4/1/2005 Minitement Trucks Lead 2006706 A1/2005 A1	Truck Center				6/28/2004			Cylinder #1 & 2 both have damage to bistons & liners	
2KS27914 Miniterran Trinch 120/2005 Q006706 4/1/2005	Truck Center			Tri-State Truck Center	6/28/2004			Flywheel housing botts backing out & breaking cut & ausing flywheel to be loose. Re-	
2KS27914 Miniferran Trucks Inc.				Southworth-Milton	1/20/2005	9029001	4/1/2005 h	SOS shows coolant in oil from the cylinder head gasket leaking	
1/4/2000 Q604042 1/18/2000 1/18/2000 1/18/2000	80		2KS27914	Minuteman Trucks, Inc	1/4/2000 Q	604042	1/18/2000 \$	#6 injector loose b/c hold down bolt snapped off in head	

Black Binder/Trans-Spec	0		Trans-Spec	10/31/2003			Heat not working, motor raps & smokes, bad torque arm rear. & install transconder	
CAT			Minuteman Trucks, Inc	11/3/2003	11/3/2003 Q600305	11/21/20	Inspect valve train - #1 valve rocker off	
black binder	-		N/A	11/12/2003			Dropped Valve.	
Black Binder/Trans-Spec	0		Trans-Spec	4/20/2004			Drop drive shaft, tap bolt holes, install spring kit, reinstall drive shaft	
CAT			Minuteman Trucks, Inc	5/14/2004 Q731097	Q731097	5/14/200	Oil leak at left lower corner of front cover. 5/14/2004 Replace front cover gasket.	
Black Binder/Milton CAT	_		Southworth-Milton	9/8/2004			Flwmeel housing cracked at right eide	
Black Binder			N/A	9/20/2004			Flywheel bolts broken (8) - replaced bolts.	
Black Binder			CAT	10/12/04 - 10/20/04			Head gasket leaking	
CAT			Southworth-Milton	10/19/2004 Q915457	Q915457	12/28/200	Broken flywheel housing caused by stress rise on housing. Flywheel housing 12/28/2004 replaced.	
CAT			Southworth-Milton	11/3/2004 Q915502	Q915502	12/28/200	rear main housing caused by wer right corner. Housing	0915467
САТ			Southworth-Milton	11/3/2004 0915467	Q915467	12/28/200	ad bottle test during advantage due to head gasket leaking at 5. A crack opened between	
CAT			Southworth-Milton	11/3/2004 Q915470	Q915470	12/28/2004	on center section of axhaust	W815504
Southworth-Milton	:		Southworth-Milton	11/22/2004			using	10±01 82
Minuteman Trucks	8400	2KS27953	Minuteman Trucks, Inc	3/9/2000			Repair kinked transmission cooler line.	
Minuteman Trucks	;		Minuteman Trucks, Inc	3/13/2000			Transmission grinds going from high to low. Noted burnt countershaft BRG & damaged main case. Strip & reman transmission.	
Diack Diriger			N/A	11/7/2001			Replaced flywheel housing.	
Black Binder/Trans-Spec			Trans-Spec	6/30/2003			Replace oil pan, refill w/ motor oil, R&R oil pan.	
Black Binder/Trans-Spec			Trans-Spec	10/27/2003			Blown Turbo.	
CAT			Minuteman Trucks, Inc	1/30/2004 Q662352		1st: 2/19/2004; 2nd: 3/18/04 (?)	Hole in side of block caused b/c exhaust valve falled & piston skirt broke. #6 piston destroyed. The exhaust valve drop destroyed piston & sent rod through block & damaged turbo.	
Black Binder/Trans-Spec			Trans-Spec	4/26/2004			Drop drive shaft, tap out bolt holes, install spring kit, & reinstall drive shaft.	

CAT			Tri-State Truck Center	3/2/2005 0.017874		1st: 4/14/2005; 2nd: 5/10/05	#6 dropped a valve & debris caused	
. TAO	000	0000000				200	Gamage to #5.	Q051553
CAT	0000	ZKSZ/893	Minuteman Trucks, Inc.	3/23/2000 Q724907	724907	7/6/2000 good.	Lighte shipping - tourid #5 injector no j good.	
			and a second sec	3/23/2000 E/44400	44400	10/23/200(10/23/2000 No fault found.	
CAT			Minuteman Trucks, Inc	3/30/2000 Q724942	724942	7/6/2000	Engine skipping - found #5 injector not firing (just replaced 6 ml. ago & replaced 7/6/2000 again).	
CAT			Minuteman Trucks, Inc.	5/12/2000 Q703553	03553	6/5/2000	Truck towed from Worcester - found #5 6/5/2000 injector top oring leaking. Replaced head	
CAT	·		Minuteman Trucks, Inc	11/7/2001 Q082333	82333	12/4/2001	Truck towed from Milbury - engine won't turn over. All 12 bolts had broken off drill out (hlock?)	
Minuteman Trucks			Minuteman Trucks, Inc	11/27/2001			Replace weak battery costumer just	
Black Binder/Trans-Spec	٠.		Trans-Spec	4/16/2004			Drop drive shaft, tap bolt holes, install spring kit reinstall drive shaft	-
CAT			Tri-State Truck Center	11/29/2004 Q991933	91933	3/17/2005	k cracked, s broken.	0910352
CAT			Tri-State Truck Center	11/29/2004 Q910352		1st: 12/21/2004, 2nd: 12/30/04, 3rd: 2/28/05		0991933
Black Binder/Trans-Spec	8600	2KS27931	Trans-Spec	10/20/2003				
CAT	•		Southworth-Milton	2000 MODELET	71		#3 cylinder has a broken valve stem - all valve heads on cylinder are gone. Install	
САТ			Tri-State Truck Center	8/20/2004 Q803935	3935	8/25/2004		
CAT			Tri-State Truck Center	8/20/2004 Q803947	3947	Flywh causing 8/25/2004 bolts.	eel housing bolts backing out ng flywheel to be loose. Replace	U803947
САТ			Southworth-Milton	10/20/2004 Q915402	5402	12/28/2004 v	_	0000000
CAT			Southworth-Milton	11/3/2004 Q956552	3552	Broken fil rise on hc 2/9/2005 replaced.	Broken flywheel housing caused by stress rise on housing. Flywheel housing. 2/9/2005 replaced.	
Minuteman Trucks 9.	0026	2KS27835	Minuteman Trucks, Inc	3/21/2000		<u> </u>	Speedometer jumps up & down & drops to zero. Order new speedometer sensor	
CAT			Minuteman Trucks, Inc	11/19/2001 Q082305	305	12/4/2001 m	Flywheel housing were loose, causing 12/4/2001 movement to crack housing	

					-														
Engine running rough & leaking oil out of flywheel area - caused by cracked flywheel housing. Changed flywheel & starter.	Damage to flywheel housing - all but 2 flywheel housing mounting bolts are broken off in engine block. Installed new flywheel housing, 2 alignment pins, & 12 bolts.	Towing provided for unusual repeat part failure. (?)	Towing provided for unusual repeat part 5/1/2002 failure. (?)	Flywheel housing.	Fuel in oil pan	Replace clutch,	Replaced flywheel housing.	Flywheel housing.	Remove driveshaft, tap bolt holes, install spring kit & rejustal drive shaft	Flywheel housing racked b/c it was loose	R&R tranny, CK volt meter gauge, check CAB level valve	Drop drive shaft, tap bolt holes, install spring kit rejustall drive shaft	Tming Gear Hso	Flywheel housing bolts backing out causing flywheel to be loose. Replace bolts.	Housing Go-Fiv	Broken flywheel housing caused by stress rise on housing. Flywheel housing	Engine skipping b/c of camshaft lobe & croller fallure. Replace camshaft & related	Repair kinked transmission cooler line	Oil leaking from between clutch housing & main case - clutch cover loose on
3/18/2002	Dams flywhu broke flywhu 3/28/2002 bolts.	5/13/2002 failure. (?)	5/1/2002							1st: 2/9/2005; 2nd: 83/4/05				T 8 8		<u> </u>	5 G S S	3 &	ŌĒ
Q159055	3/18/2002 Q169291	3/18/2002 0203345	3/19/2002 0194952										Dealer Claim TS108268	Dealer Claim TS108269	Dealer Claim MT62609				
11/19/2001 Q159055	3/18/2002	3/18/2002	3/19/2002	5/18/2002	5/6/2003	5/29/2003	10/20/2003	4/29/2004	5/4/2004	12/30/2004 Q956322	5/5/2003	5/4/2004	Dealer Cla 8/20/2004 TS108268	Dealer Clai 8/20/2004 TS108269	Dealer Cit 11/3/2004 MT62609	11/22/2004	10/4/2004	3/24/2000	
Minuteman Trucks, Inc	Minuteman Trucks, Inc	Minuteman Trucks, Inc	Minuteman Trucks, Inc	N/A	Trans-Spec	Trans-Spec	NA	Trans-Spec	Trans-Spec	Southworth-Milton	Trans-Spec	Trans-Spec	Tri-State Truck Center	Tri-State Truck Center	N/A	Southworth-Milton	Southworth-Milton	Minuteman Trucks, Inc	
											2KS27791						2KS13643	2FWYEWEB XYAF57177	
	·										9800								
CAT	САТ	CAT	CAT Block Biodoc	Diack billider	Black Binder/Trans-Spec	Black Binder/Trans-Spec Black Binder		Black Binder/Trans-Spec	Black Binder/Trans-Spec	CAT	Black Binder/Trans-Spec 9800	Black Binder/Trans-Spec	CAT - SIMSi	CAT - SIMSi	CAT - SIMSi	Southworth-Milton.	Southworth-Milton	Minuteman Trucks.	Minitement Tricks